# LTC-114x Software

#### 1 Current Release Notes, Version 0.80

#### 12 February 2019

LTC Configuration Software Version 0.80; LTC-114x Firmware Version 0.80

#### **Supported Devices**

• LTC-1141/1142: Hardware Versions 1.30 – 1.31

#### **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

• LDD DSO number of points increased from 8'192 points to 16'777'216 points. The Configuration Software creates a .csv file, which is located next to the .exe file of the Configuration Software.

#### **Resolved Issues**

- Configuration Software
  - o None

- LDD DSO graph cannot chart 16M points. Please disable the graph and use the .csv file, which is located next to the .exe file of the Configuration Software.
- LDD Auto Tuning not yet available.
- The analog output cannot be controlled.
- Firmware only issues
  - The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close to the limitation, an error message is thrown.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 1 (15)
	Release Notes	Family	12.02.19 ML	5203M

#### 17 October 2018

LTC Configuration Software Version 0.71; LTC-114x Firmware Version 0.70

# **Supported Devices**

• LTC-1141/1142: Hardware Versions 1.30 - 1.31

#### **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

o None

## **Resolved Issues**

- Configuration Software
  - The IP Address and a few other values have not been updated periodically. (Only during the connecting phase)

- LDD Auto Tuning not yet available.
- The analog output cannot be controlled.
- Firmware only issues
  - $\circ$   $\;$  The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close to the limitation, an error message is thrown.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 2 (15)
	Release Notes	Family	12.02.19 ML	5203M

#### 17 August 2018

LTC Configuration Software Version 0.70; LTC-114x Firmware Version 0.70

## **Supported Devices**

• LTC-1141/1142: Hardware Versions 1.30 – 1.31

#### **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

- Configuration Software
  - The IO window shows the PBC analog input voltage. Currently there is no further usage of this value.
  - The LDD Graph acquired values are saved to the LddChartOutput.csv file in the program's folder.
  - Export option to export a list with all possible error messages added.
- Firmware
  - The TEC current measurement can be calibrated by the manufacturer. Note: downgrading the firmware on a board delivered with this firmware or newer, results in losing this calibration.
  - GPIO9 and GPIO10 are used to measure the voltage across them differentially. Currently there is no further usage of this value.

## **Resolved Issues**

- Configuration Software
  - Sometimes the application did not start properly on slower PC systems, because of a multithreading conflict. → Thread synchronization optimized.
  - Parameters like Temperature Sensor Type are now only imported if the serial number of the XML file is the same (like the TEC Service Software does).
  - Removed the possibility to update older firmware versions with a newer Configuration Software version. Otherwise it is possible to skip the Firmware Update Lock feature.
- Firmware
  - Hardware test functionality fixed.
  - o The MS (Meerstetter Set) command was missing.
  - The ?VL command was missing.
  - The LTC webpage doesn't show the wrong name for LTC-1142 devices anymore.
  - The LDD output stage power dissipation monitoring error 20400 was sometimes thrown too early or too late.  $\rightarrow$  LDD output stage power dissipation monitoring optimized.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 3 (15)
	Release Notes	Family	12.02.19 ML	5203M

- LDD Auto Tuning not yet available.
- The analog output cannot be controlled.
- Firmware only issues
  - The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close to the limitation, an error message is thrown.

meerstetter	Software	LTC-	12.04.16 TB	Page 4 (15)
	Release Notes	Family	12.02.19 ML	5203M

#### 24 May 2017

LTC Configuration Software Version 0.60; LTC-114x Firmware Version 0.60

# **Supported Devices**

• LTC-1141/1142: Hardware Versions 1.30 – 1.31

#### **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

- Flexible GPIO configuration function, debounce time and polarity inversion. Check IO window.
- Configuration Software:
  - Status bar added to each window.
  - Custom Lock Configuration.
- Firmware:
  - Ethernet: The device reports now a host name like "LTC-1141\_SerialNr16".

#### **Resolved Issues**

- Configuration Software
  - The appearance was different on various Windows versions.
  - The shown error message was wrong, if the user has imported a wrong formatted lookup table.
  - The shown error message was wrong, if the user has connected a device with a too old or too new firmware.
  - $\circ$   $\,$  The debounce time in the IO window was not in the right format.
  - The software may have crashed during device connect. Fixed.
  - The software may have consumed too much CPU power if the TEC Chart was open for several hours. → The chart history has been limited to 2h.
- Firmware:
  - The UART / RS485 interface may have blocked sometimes.
  - o The lookup table sample rate processing usage in the system was slightly wrong.

- LDD Auto Tuning not yet available.
- The list with all possible error messages is not yet available.
- The analog output cannot be controlled.
- Firmware only issues
  - The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close at the limitation, an error message is thrown.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 5 (15)
	Release Notes	Family	12.02.19 ML	5203M

13 November 2016

LTC Configuration Software Version 0.50; LTC-114x Firmware Version 0.51

# **Supported Devices**

- LTC-1141: Hardware Versions 1.30 1.31
- LTC-1142: Hardware Versions 1.30 1.31

# **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

• None

# **Resolved Issues**

- Bug: External enable reported wrong status at high frequency
- Bug: TEC Stable had no effect when LDD Enable was set to Digital IO

- LDD Auto Tuning not yet available.
- The list with all possible error messages is not yet available.
- No functionality available for the GPIO pins.
- The analog output cannot be controlled.
- Firmware only issues
  - o To change the IP Settings DHCP mode, a system reset is required to apply.
  - The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close at the limitation, an error message is thrown.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 6 (15)
	Release Notes	Family	12.02.19 ML	5203M

2 November 2016

LTC Configuration Software Version 0.50; LTC-114x Firmware Version 0.50

# **Supported Devices**

- LTC-1141: Hardware Versions 1.30 1.31
- LTC-1142: Hardware Versions 1.30 1.31

## **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

- Add: Some fixed Digital IO Configurations
  - LDD Enable source option: Enable upon an external positive edge on the Digital IO X3 Pin 5
  - Collective Error out on Digital IO X3 Pin 6 (High = at least one error is present)

## **Resolved Issues**

None

- LDD Auto Tuning not yet available.
- The list with all possible error messages is not yet available.
- No functionality available for the GPIO pins.
- The analog output cannot be controlled.
- Firmware only issues
  - o To change the IP Settings DHCP mode, a system reset is required to apply.
  - $\circ$   $\;$  The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close at the limitation, an error message is thrown.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 7 (15)
	Release Notes	Family	12.02.19 ML	5203M

26 October 2016

LTC Configuration Software Version 0.40; LTC-114x Firmware Version 0.41

# **Supported Devices**

- LTC-1141: Hardware Versions 1.30 1.31
- LTC-1142: Hardware Versions 1.30 1.31

# **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

• Add: Sync and LED output to IO's. Sync on X3.3 and LED on X3.4. This is temporary and will be soon upgraded with a fully user configurable IO configuration system.

# **Resolved Issues**

• None

- LDD Auto Tuning not yet available.
- The list with all possible error messages is not yet available.
- No functionality available for the GPIO pins.
- The analog output cannot be controlled.
- Firmware only issues
  - $\circ$   $\,$  To change the IP Settings DHCP mode, a system reset is required to apply.
  - $\circ$   $\;$  The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close at the limitation, an error message is thrown.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 8 (15)
	Release Notes	Family	12.02.19 ML	5203M

18 October 2016

LTC Configuration Software Version 0.40; LTC-114x Firmware Version 0.40

# **Supported Devices**

- LTC-1141: Hardware Versions 1.30 1.31
- LTC-1142: Hardware Versions 1.30 1.31

# **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

Add: Support for PD1 and PD10

## **Resolved Issues**

None

- LDD Auto Tuning not yet available.
- The list with all possible error messages is not yet available.
- No functionality available for the GPIO pins.
- The analog output cannot be controlled.
- Firmware only issues
  - o To change the IP Settings DHCP mode, a system reset is required to apply.
  - The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close at the limitation, an error message is thrown.

engineering	Software	LTC-	12.04.16 TB	Page 9 (15)
	Release Notes	Family	12.02.19 ML	<b>5203M</b>

19 June 2016

LTC Configuration Software Version 0.30; LTC-114x Firmware Version 0.31

# **Supported Devices**

- LTC-1141: Hardware Versions 1.30 1.31
- LTC-1142: Hardware Versions 1.30 1.31

## **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

Formal Modification: Added new Supported Devices

# **Resolved Issues**

- Bug: Buffer Overflow in parameter system.
- Bug: New parameter were not limited correctly.

- LDD Auto Tuning not yet available.
- The list with all possible error messages is not yet available.
- No functionality available for the GPIO pins.
- The analog output cannot be controlled.
- Firmware only issues
  - o To change the IP Settings DHCP mode, a system reset is required to apply.
  - The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close at the limitation, an error message is thrown.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 10 (15)
	Release Notes	Family	12.02.19 ML	5203M

#### 7 June 2016

LTC Configuration Software Version 0.30; LTC-1141 Firmware Version 0.31

# **Supported Devices**

• LTC-1141: Hardware Versions 1.30 - 1.30

## **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

None

## **Resolved Issues**

- Bug: Buffer Overflow in parameter system.
- Bug: New parameter were not limited correctly.

- LDD Auto Tuning not yet available.
- The list with all possible error messages is not yet available.
- No functionality available for the GPIO pins.
- The analog output cannot be controlled.
- Firmware only issues
  - $\circ$   $\,$  To change the IP Settings DHCP mode, a system reset is required to apply.
  - The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close at the limitation, an error message is thrown.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 11 (15)
	Release Notes	Family	12.02.19 ML	5203M

#### 27 May 2016

LTC Configuration Software Version 0.30; LTC-1141 Firmware Version 0.30

# **Supported Devices**

• LTC-1141: Hardware Versions 1.30 - 1.30

#### **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

- Add: LDD Graph
- Add: LDD Lookup Table: Custom waveform generation. (You may have to download a lookup table file to resolve the parameter system error after updating.)
- Add: LDD Slew Rate Limiter

#### **Resolved Issues**

- Configuration Software cannot connect to the device → Solved, works now
- Timebase of PID Controller for LDD was wrong. You may readjust the PID parameters. Multiply Ki and Kd with 1E-3 to adjust the parameters.
- Optimized TEC PWM to be able to achieve 16V output on all devices.

- LDD Auto Tuning not yet available.
- The list with all possible error messages is not yet available.
- No functionality available for the GPIO pins.
- The Analog output cannot be controlled.
- Firmware only issues
  - $\circ$   $\,$  To change the IP Settings DHCP mode, a system reset is required to apply.
  - $\circ$   $\;$  The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close at the limitation, an error message is thrown.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 12 (15)
	Release Notes	Family	12.02.19 ML	5203M

- Configuration Software only issues:
  - TEC Temperature Graph:
    - May stress the CPU too much if too much data is in the graph. Workaround: Restart the Configuration Software.
    - The time axis labels do not have enough time resolution.
  - No hint if unsaved Parameters are present.

meerstetter	Software	LTC-	12.04.16 TB	Page 13 (15)
engineering	Release Notes	Family	12.02.19 ML	<b>5203M</b>

#### 14 April 2016

LTC Configuration Software Version 0.20; LTC-1141 Firmware Version 0.21

# **Supported Devices**

• LTC-1141: Hardware Versions 1.30 – 1.30

## **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

None

# **Resolved Issues**

• Fixed manufacturing issue of LTC-1141-150

# Known Issues or Not yet Implemented Main Features

- No graph functionality available for the LDD current and analog input. The firmware does not log the signals.
- LDD Auto Tuning not yet available.
- The list with all possible error messages is not yet available.
- No functionality available for the GPIO pins.
- The Analog output cannot be controlled.
- No customized waveform can be defined.
- Firmware only Issues
  - o To change the IP Settings DHCP mode, a system reset is required to apply.
  - The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close at the limitation, an error message is thrown.
- Configuration Software only issues:
  - TEC Temperature Graph:
    - May stress the CPU too much if too many data is in the graph. Workaround: Restart the Configuration Software.
    - The time axis labels do not have enough time resolution.
  - The Ethernet connection does not work. (only USB)
  - No hint if unsaved Parameters are present.

#### 13 Old Release Notes, Version 0.20

#### 13 April 2016

LTC Configuration Software Version 0.20; LTC-1141 Firmware Version 0.20

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 14 (15)
	Release Notes	Family	12.02.19 ML	5203M

# **Supported Devices**

• LTC-1141: Hardware Versions 1.30 – 1.30

# **New and Improved Features**

The current release features the following enhancements. Refer to the user manual or the communication protocol specification for further information:

• First official release version

# **Resolved Issues**

None

- No graph functionality available for the LDD current and analog input. The firmware does not log the signals.
- LDD Auto Tuning not yet available.
- The list with all possible error messages is not yet available.
- No functionality available for the GPIO pins.
- The Analog output cannot be controlled.
- No customized waveform can be defined.
- Firmware only Issues
  - $\circ$   $\,$  To change the IP Settings DHCP mode, a system reset is required to apply.
  - The supply voltage values may not be updated sometimes.
  - If the TEC Output Stage voltage and current limitations are changed while the corresponding value is running close at the limitation, an error message is thrown.
- Configuration Software only issues:
  - TEC Temperature Graph:
    - May stress the CPU too much if too many data is in the graph. Workaround: Restart the Configuration Software.
    - The time axis labels do not have enough time resolution.
  - The Ethernet connection does not work. (only USB)
  - No hint if unsaved Parameters are present.

meerstetter engineering	Software	LTC-	12.04.16 TB	Page 15 (15)
	Release Notes	Family	12.02.19 ML	5203M